

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2020

Submitted Date:

06/02/2020

Document Number:

698600321

**FIELD INSPECTION FORM**Loc ID 312132 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10374

Name of Operator: RED MOUNTAIN RESOURCES LLC

Address: 6538 JUNGFRAU WAY

City: EVERGREEN State: CO Zip: 80439

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218393	WELL	PA	05/30/2018	OW	075-05078	COLORADO STATE (OWP) J-18	PA

**General Comment:**

This is an orphaned well inspection. Inspection completed to document progress and completion of equipment salvage and decommissioning task. Well previously plugged and abandoned 5/30/2018.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable documents and pictures.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access maintained CR onto visible two track road.		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Other	Pump Jack			
Comment:	After pump jack was removed impacted soils were excavated from site. Stained soils were under the prime mover motor (lube oil) area and were not completely removed based on contract limitations. Additional clean up will be required.			
Corrective Action:	Remediate impacted soil.			Date:

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 0		
Comment:	Excavated and removed (4) anchors.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Production flowline was excavated, cement plugged, and abandoned at the start and end points. All other flowlines at well site were removed.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:	Disassembled and removed.		
Corrective Action:		Date:	

<b>Venting:</b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>	
Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	218393	Type:	WELL	API Number:	075-05078	Status:	PA	Insp. Status:	PA

--

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Equipment salvage and decommissioning task is complete. Due to impacted soils discovered under the pumping unit motor site will require environmental task for remediation and clean up prior to reclamation task.	stjohnw	06/02/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402411349	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164739">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164739</a>
698600322	Daily Report.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164728">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164728</a>
698600323	Daily Report.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164729">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164729</a>
698600324	Daily Report.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164730">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164730</a>
698600325	Daily Report.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164731">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164731</a>
698600327	Daily Report.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164732</a>
698600328	Daily Report.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164733">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164733</a>
698600329	Daily Report.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164734">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164734</a>
698600330	Daily Report.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164735">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164735</a>
698600331	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164736">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164736</a>