

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2020

Submitted Date:

06/02/2020

Document Number:

698600332**FIELD INSPECTION FORM**Loc ID 312133 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10374Name of Operator: RED MOUNTAIN RESOURCES LLCAddress: 6538 JUNGFRAU WAYCity: EVERGREEN State: CO Zip: 80439**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218397	WELL	PA	06/07/2018	OW	075-05083	STATE (OWP) B-1	PA

General Comment:

This is an orphaned well inspection. Inspection completed to document progress and completion of equipment salvage and decommissioning task.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable documents and pictures.

Location

Lease Road:			
Type	Access		
comment:	Access off maintained CR onto visible dirt and gravel two track road.		
Corrective Action	L	Date:	

Overall Good: ☐

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
Other	Pump Jack			
Comment:	After removing pumping unit area of impacted soil identified under prime mover motor. Due to contract limitations impacted soil was not completely removed and will require further remediation.			
Corrective Action:	Remediate impacted soil.			Date:

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 0		
Comment:	Disassembled and removed.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:	Excavated and removed (4) anchors.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Cement plugged and abandoned production flowline at both end points. All other flowlines were removed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment:	Well previously plugged and abandoned 6/7/2018.		
Corrective Action:		Date:	

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	218397	Type:	WELL	API Number:	075-05083	Status:	PA	Insp. Status:	PA

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: [Impacted soil will need to be remediated prior to reclamation task.](#)

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Equipment salvage and decommissioning task completed. Impacted soil discovered after removing pumping unit under prime mover motor (lube oil leak) will require environmental task and further remediation prior to reclamation task.	stjohnw	06/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402411419	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164800
698600333	Daily report.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164791
698600334	Daily report.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164792
698600335	Daily report.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164793
698600336	Daily report.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164794
698600337	Daily report.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164795
698600338	Daily report.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164796
698600339	Daily report.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164797
698600340	Daily report.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164798
698600341	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164799