

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402415299

Date Received:
06/08/2020

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1801 BROADWAY #1000
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Recipient, Single</u>		<u>Inspections@catamountep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901869
Inspection Date: 06/03/2020 FIR Submit Date: 06/04/2020 FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464
Address: 1801 BROADWAY #1000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 326652

Location Name: ARVIL BROWN MV-N33N9W Number: 15SWSE County: LA PLATA
Qtrqr: SWSE Sec: 15 Twp: 33N Range: 9W Meridian: N
Latitude: 37.099390 Longitude: -107.810100

FACILITY - API Number: 05-067-00 Facility ID: 261382

Facility Name: ARVIL BROWN MV Number: 1
Qtrqr: SWSE Sec: 15 Twp: 33N Range: 9W Meridian: N
Latitude: 37.099390 Longitude: -107.810100

CORRECTIVE ACTIONS:

1 CA# 139512

Corrective Action: Control weeds. Date: 07/04/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: The surface equipment and ROW where the weed infestation is located do not belong to Catamount.

COGCC Decision: **Not Approved**

COGCC Representative: Request is denied. Upon review of flowline data mapping it appears that the flowline system and associated weeds shown in the photo are associated with a BP flowline system. However, numerous additional Russian knapweeds (in the thousands) are established on the fill slopes of the Catamount location. Recommend working with BP to eliminate the Russian knapweed infestation.

Future factual review requests need to supply official documentation that supports the request.

COGCC Supervisor: Request is denied. Upon review of flowline data mapping it appears that the flowline system and associated weeds shown in the photo are associated with a BP flowline system. However, numerous additional Russian knapweeds (in the thousands) are established on the fill slopes of the Catamount location. Recommend working with BP to eliminate the Russian knapweed infestation.

Future factual review requests need to supply official documentation that supports the request.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: _____

Title: Geo/Eng Tech

Date: 6/8/2020 6:05:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402415299	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files