

Inspection Photos

Location Name: LARAMIE ENERGY LLC Red Mountain Ranch /4-6 Pad

Location ID: 334512



Network time is not synchronize
Local: Jun 9, 2020 at 12:31:16 PM MD
+39.2210, -107.890

Photo #1330 from entrance to location



Network time is not synchronize
Local: Jun 9, 2020 at 12:43:01 PM MD
+39.2206, -107.890

Photo #1331 Drain valve on tank #4-5 dripping condensate.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Red Mountain Ranch /4-6 Pad

Location ID: 334512



Photo #1332 Drain valve on tank #4-5 dripping condensate.