

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/09/2020

Submitted Date:

06/09/2020

Document Number:

699301927

FIELD INSPECTION FORM
 Loc ID 319537 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

21 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436667	WELL	PR	12/19/2014	OW	123-39214	Mumby State 4D-36H P266	PR
436668	WELL	PR	10/01/2019	OW	123-39215	Mumby State 4H-36H P266	PR
436669	WELL	PR	12/19/2014	OW	123-39216	Mumby State 4E-36H P266	PR
436670	WELL	PR	12/19/2014	OW	123-39217	Mumby State 4F-36H P266	PR
436671	WELL	PR	10/01/2019	OW	123-39218	Mumby State 4G-36H P266	PR
436672	WELL	PR	12/19/2014	OW	123-39219	Mumby State 4C-36H P266	PR
436673	WELL	PR	12/19/2014	OW	123-39220	Mumby State 4B-36H P266	PR
436677	WELL	PR	04/01/2019	OW	123-39222	Mumby State 4A-36H P266	PR
451371	TANK BATTERY	AC	07/12/2017		-	Mumby State battery	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate x 8		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	damaged shed, unused misc. parts/trash at tank battery		
Corrective Action:	comply with Rule 603.f	Date:	06/23/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:	Hog fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	hog fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:

Type: VRU	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 20		
Comment:	automation and electric panels		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	all appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Hydraulic lift system		
Corrective Action:		Date:	
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	shares containment with condensate tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

CONDENSATE	12	500 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	436667	Type:	WELL	API Number:	123-39214	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436668	Type:	WELL	API Number:	123-39215	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436669	Type:	WELL	API Number:	123-39216	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436670	Type:	WELL	API Number:	123-39217	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436671	Type:	WELL	API Number:	123-39218	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436672	Type:	WELL	API Number:	123-39219	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436673	Type:	WELL	API Number:	123-39220	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436677	Type:	WELL	API Number:	123-39222	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Facility ID: 451371 Type: TANK API Number: - Status: AC Insp. Status: AC

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 6/9/2020 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:</p> <p style="text-align: right;">Mumby State 36H-</p> <p>P266 at Location # 319537 in Weld County Colorado.</p> <p>While there, I observed a multi well pad and tank battery.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>603.f housekeeping: Trash damaged metal shed outside of TB fence and trash inside of metal berm at TB, CA date 6-23-2020. See attached photos 8, 9, 10 and 11.</p> <p>Location is dry, weather is cloudy/windy.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	06/09/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301928	well site pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5170177
699301929	TB pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5170178