

Behrens Resources INC, State-Craig 3-16
005-06876

Inspection #688307987

6/8/2020

Tank Battery Inspection



Colorado Oil and Gas Conservation Commission
39.61459, -104.32364, 5574.1ft, 234°
06/08/2020 01:26:34 PM




Colorado Oil and Gas Conservation Commission
39.61462, -104.32364, 5570.9ft, 359°
06/08/2020 01:26:39 PM




Colorado Oil and Gas Conservation Commission
39.61505, -104.32356, 5570.9ft, 187°
06/08/2020 01:25:03 PM



Colorado Oil and Gas Conservation Commission
39.61499, -104.32366, 5567.6ft, 126°
06/08/2020 01:25:27 PM

A photograph showing a cross-section of a sandy soil profile. The soil is light brown and appears to be composed of fine sand and silt. There are some darker, more clumpy areas interspersed within the lighter sand. A pencil is placed horizontally in the lower-left portion of the image to provide a sense of scale. The pencil has a grey eraser, a red band, and a dark tip. The background shows more of the same soil surface, which is uneven and eroded. The lighting is bright, suggesting a sunny day.

Colorado Oil and Gas Conservation Commission
39.61499, -104.32365, 5564.3ft, 83°
06/08/2020 01:25:29 PM



Colorado Oil and Gas Conservation Commission
39.61537, -104.3236, 5580.7ft, 255°
06/08/2020 01:30:50 PM



Colorado Oil and Gas Conservation Commission
39.61498, -104.32365, 5567.6ft, 241°
06/08/2020 01:25:35 PM



Stained soil in treater shed.

Colorado Oil and Gas Conservation Commission
39.61487, -104.32367, 5577.4ft, 207°
06/08/2020 01:25:58 PM