

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:		Date:			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		,	
Comment:	Shared battery services at location number: 409310					
Corrective Action:					Date:	

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 270090 Type: WELL API Number: 123-21831 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>On Wednesday, June 10, 2020 at 10:02, I, Craig Carlile conducted an on-site inspection at: 332097 MCDONALD-63N67W 4NWNE Operated by: Anadarco While there I observed: Weeds at wellhead. Possible compliance issues observed: None Weather: Skies: Partly Cloudy, Wind: Calm, Temp68 Degrees F Corrective Action Dialogue: Comply with Rule 603.f .</p> <p>This is a summary of the inspection report.</p>	carlilec	06/10/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690005952	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5170771