

Inspection Photos
Location Name: Stamp 31-2 Historical Release
Spill ID 476473; Rem 15517



Photo 1 –Northern sidewall of excavation. Groundwater seeping in through deepest portions of the excavation



Photo 2 – Western sidewall of excavation. Groundwater seeping in through deepest portions of the excavation

Inspection Photos
Location Name: Stamp 31-2 Historical Release
Spill ID 476473; Rem 15517



Photo 3 – Stained soil observed in southeast portion of the excavation.



Photo 4 – Stained soil observed in sidewalls under excavator (southeast portion of the excavation).

Inspection Photos
Location Name: Stamp 31-2 Historical Release
Spill ID 476473; Rem 15517



Photo 5 – Orange safety fencing around inactive parts of the excavation.



Photo 6 – Southern sidewall of excavation; stained soil observed in sidewalls under excavator. Orange safety fencing around inactive excavation extents.

Inspection Photos
Location Name: Stamp 31-2 Historical Release
Spill ID 476473; Rem 15517



**Photo 7 – Eastern sidewall of excavation.
Goundwater seeping in through floor of excavation.**



Photo 8 – Tracking pad at beginning of access road.