

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2020

Submitted Date:

06/10/2020

Document Number:

700401912**FIELD INSPECTION FORM**Loc ID 315090 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230238	WELL	SI	01/01/2017	OW	103-07897	FEDERAL 1-17	SI

General Comment:

On 6-9-2020 inspector Rick Moran conducted a follow up inspection at Lasso well Federal 1-17 in Rio Blanco county of:

- 1) FIR document 700400548 dated 3-18-2020.
- 2) Warning letter 401967037 dated 3-11-2019 for no current MIT.

The following compliance issues were resolved:

- 1) "911" was added to road sign located 4 miles away from well.

The following compliance issues are uncompleted:

- 1) No current MIT.

This is a summary of inspection report 700401912.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Propane tank.			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		

Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 230238 Type: WELL API Number: 103-07897 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: [Last recorded production July 2017. No MIT on file.](#)[No current MIT on record or delinquent as required by Rule 326](#)

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Blowdown

Lined:

Pit ID:

Lat:

Long:

Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date: **Fencing:**Fencing Type: WildlifeFencing Condition: AdequateComment:

Corrective Action

Date: **Netting:**Netting Type: MeshNetting Condition: GoodComment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment:

Corrective

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700401913	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171227