

Inspection Photos

6/5/2020, 6/9/2020

Operator: TEP ROCKY MOUNTAIN LLC #
96850

Location ID: 475753

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 475753



Photo 1: Photo taken from the south end of the Location facing northwest. Photos 1-4 provide an overview of the constructed pad from northwest, north, northeast, to east. Total area of disturbance ~3 acres. Pad area ~2.7 acres.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 475753



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 475753



Photo 5: Photo taken from the south end of the Location, facing south. Photo shows soil stockpile on the Location; No other soil stockpiles appear to have been constructed. Photo also shows Operator has installed hay bale and wattle BMPs at the toe of the soil stockpile. Additional BMPs to stabilize the soils of the stockpile appear missing, or insufficient.



Photo 6: Photo taken from the soil stockpile. Photo shows Operator has installed hay bale and wattle BMPs at the toe of the soil stockpile. BMPs have filled with sediment and are no longer in proper functioning condition. BMPs used in conjunction with hay bale/wattles are missing, or insufficient to stabilize the soils of the stockpile.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 475753



Photo 7: Photo taken from the south of the Location, facing north. Photo shows Operator appears to have placed/piled woody vegetation on the south end of the pad, and next to the soil stockpile. This is considered debris and needs to be properly removed/disposed.



Photo 8: See comments under photo 7.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 475753



Photo 9: See comments under photo 7.



Photo 10: Photo taken from the north of the Location, facing east. shows Operator appears to have placed/piled woody vegetation north the pad. This is considered debris and needs to be properly removed/disposed. Photo also shows disturbance due to Operator's activities. Areas will require reclamation.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 475753



Photo 11: Photo taken from the northeast end of the Location, facing south. Photos 11-13 provide an overview of the Location from south, southwest to west.



Photo 12: See comments under photo 11.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 475753



Photo 13: See comments under photo 11.



Photo 14: Photo taken from the north end of the Location, facing north. Photo shows soils on cut slopes. BMPs to stabilize and protect slopes appear insufficient or missing; Erosion degradation evident.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 475753



Photo 15: Photo taken from the west end o the Location, facing west. Photo shows soils on cut slopes. BMPs to stabilize and protect slopes appear insufficient or missing; Erosion degradation evident.



Photo 16: Photo shows fuel container in proper containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 475753



Photo 17: Photo taken from the east end of the Location, facing north. Photo shows soils on the fill slopes. BMPs to stabilize and protect slopes appear insufficient or missing



Photo 18: Photo taken from the access road, south of the Location. Photo shows area where stormwater runoff from the pad and access road concentrates and discharges.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 475753



Photo 19: Continued from photo 18. Photo shows erosion degradation and sediment deposition.



Photo 20: Continued from photo 18. Photo shows point where stormwater discharges. Photo shows that the Wattle BMP is not in proper functioning condition; Stormwater appears to have cut under the wattle resulting and erosion degradation and off-site sediment discharge.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 475753



Photo 21: Photo taken from the access road, facing southwest. Photo shows areas where sediment deposition has begun filling the wattle BMPs. Advised maintenance prior to BMP failure.



Photo 22: Photo taken from where access road crosses drainage. Photo shows BMPs to stabilize access road appear missing or insufficient.