

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/10/2020

Submitted Date:

06/10/2020

Document Number:

696301923

**FIELD INSPECTION FORM**

Loc ID 430722 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430720	WELL	PR	04/01/2017	OW	123-36267	TIMBRO LD29-78HN	PR
430721	WELL	PR	04/01/2019	OW	123-36268	TIMBRO LD19-73HN	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Timbro LD29-78H is missing Wellhead Sign, see photos		
Corrective Action:	Comply with Rule 210.b.	Date:	07/10/2020

**Emergency Contact Number:**

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Wellhead parts at LD10-73HN Wellhead, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	07/10/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:			Date: _____

**Equipment:**

Type: Plunger Lift	# 2			corrective date
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:	Appear to be plumbed to surface			
Corrective Action:			Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date: _____

**Flaring:**

Type			
Comment:			
Corrective Action:			Date: _____

**Inspected Facilities**

Facility ID: 430720 Type: WELL API Number: 123-36267 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

Facility ID: 430721 Type: WELL API Number: 123-36268 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspeccion. Timbro LD29-78H is missing Wellhead Sign. Unused Wellhead parts at LD19-73HN Wellhead.</a>	petrie	06/10/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301924	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171316">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171316</a>