

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/11/2020

Submitted Date:

06/11/2020

Document Number:

700700864

FIELD INSPECTION FORM

Loc ID 334888	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635				Findings: 37 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211419	WELL	PR	01/18/1998	GW	045-07179	JUHAN RMV 83-34	PR
296694	WELL	PR	06/23/2008	GW	045-16102	SAVAGE RWF 324-34	PR
297602	WELL	PR	08/08/2008	GW	045-16891	SAVAGE RWF 13-34	PR
297603	WELL	PR	05/31/2009	GW	045-16890	SAVAGE RWF 14-34	PR
297604	WELL	PR	08/08/2008	GW	045-16889	SAVAGE RWF 314-34	PR
297633	WELL	PR	06/01/2011	GW	045-16894	SAVAGE RWF 332-34	PR
297634	WELL	PR	03/31/2010	GW	045-16895	SAVAGE RWF 24-34	PR
297635	WELL	PR	03/31/2010	GW	045-16896	SAVAGE RWF 423-34	PR
297638	WELL	PR	02/16/2011	GW	045-16899	SAVAGE RWF 444-34	PR
297639	WELL	PR	06/01/2011	GW	045-16900	SAVAGE RWF 44-34	PR
297640	WELL	PR	06/01/2011	GW	045-16901	SAVAGE RWF 443-34	PR
297641	WELL	PR	03/31/2010	GW	045-16902	SAVAGE RWF 334-34	PR
297642	WELL	PR	06/01/2011	GW	045-16903	SAVAGE RWF 34-34	PR
297643	WELL	PR	06/01/2011	GW	045-16905	SAVAGE RWF 333-34	PR
297644	WELL	PR	06/01/2011	GW	045-16906	SAVAGE RWF 33-34	PR
297645	WELL	PR	09/20/2010	GW	045-16907	SAVAGE RMV 81-34	PR
297646	WELL	PR	05/31/2010	GW	045-16908	SAVAGE RMV 82-34	PR
297647	WELL	PR	06/01/2011	GW	045-16909	SAVAGE RMV 74-34	PR
417814	WELL	PR	06/30/2011	GW	045-19630	Savage RWF 31-3	PR
417815	WELL	PR	07/20/2011	GW	045-19631	Savage RWF 431-3	PR
417816	WELL	PR	07/20/2011	GW	045-19632	Savage RWF 341-3	PR

417817	WELL	PR	06/30/2011	GW	045-19633	Savage RWF 41-3	PR
417818	WELL	PR	06/30/2011	GW	045-19634	Savage RWF 531-3	PR
417819	WELL	PR	07/13/2011	GW	045-19635	Savage RWF 331-3	PR
417820	WELL	PR	07/13/2011	GW	045-19636	Savage RWF 432-3	PR
417821	WELL	PR	07/20/2011	GW	045-19637	Savage RWF 342-3	PR
417822	WELL	PR	06/30/2011	GW	045-19638	Savage RWF 332-3	PR
417854	WELL	PR	06/30/2011	GW	045-19644	Savage RWF 441-3	PR

General Comment:

COGCC Inspection Report Summary

On Thursday 6/11/20 at approximately 11:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 83-34, at Location # 334888 in Garfield Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed:

- Secondary containment under transfer pump needs maintenance.
- Slope on east side of tanks is eroding and is in need of proper BMP's.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Secondary containment under transfer pump needs maintenance.		
Corrective Action:	repair secondary containment	Date:	07/13/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 16		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	water transfer pump		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	chemical tanks at well heads		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:	shared containment with condensate tanks and produced water tanks					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		,
Comment:		500 gallon diesel tank			
Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLS	STEEL AST		,
Comment:		shared containment with condensate tanks			
Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211419	Type:	WELL	API Number:	045-07179	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	296694	Type:	WELL	API Number:	045-16102	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297602	Type:	WELL	API Number:	045-16891	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297603	Type:	WELL	API Number:	045-16890	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297604	Type:	WELL	API Number:	045-16889	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297633	Type:	WELL	API Number:	045-16894	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297634	Type:	WELL	API Number:	045-16895	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297635	Type:	WELL	API Number:	045-16896	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID:	297638	Type:	WELL	API Number:	045-16899	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297639	Type:	WELL	API Number:	045-16900	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297640	Type:	WELL	API Number:	045-16901	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297641	Type:	WELL	API Number:	045-16902	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297642	Type:	WELL	API Number:	045-16903	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297643	Type:	WELL	API Number:	045-16905	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297644	Type:	WELL	API Number:	045-16906	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297645	Type:	WELL	API Number:	045-16907	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	297646	Type:	WELL	API Number:	045-16908	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297647	Type:	WELL	API Number:	045-16909	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417814	Type:	WELL	API Number:	045-19630	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417815	Type:	WELL	API Number:	045-19631	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417816	Type:	WELL	API Number:	045-19632	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417817	Type:	WELL	API Number:	045-19633	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417818	Type:	WELL	API Number:	045-19634	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417819	Type:	WELL	API Number:	045-19635	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	417820	Type:	WELL	API Number:	045-19636	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417821	Type:	WELL	API Number:	045-19637	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417822	Type:	WELL	API Number:	045-19638	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417854	Type:	WELL	API Number:	045-19644	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Berms		Berms				
Ditches		Ditches				

Comment: [Slope on east side of tanks is eroding](#)Corrective Action: [Install proper BMP's behind tank battery on east side of location, see photos.](#)

Date: 08/11/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	422633	2213250	
	422633	2213250	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700872	photos for RMV 83-34	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5172222