

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2020

Submitted Date:

06/11/2020

Document Number:

696201392**FIELD INSPECTION FORM**Loc ID 335211 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, "		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291568	WELL	PR	09/01/2011	GW	045-14441	CHEVRON-MARATHON 41A-22D	RI
291570	WELL	PR	09/01/2011	GW	045-14440	CHEVRON-MARATHON 14D-14D	RI
335211	LOCATION	AC			-	CHEVRON-MARATHON- 66S97W 23NWNW	RI

General Comment:

On 6/09/2020, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Caerus Piceance's Chevron-Marathon-66S97W23 NWNW Location in Garfield County, Colorado.

This inspection is a followup to Inspection No. 696201183 to document compliance with the following corrective actions:

308A.b.(2)F: "As Drilled" coordinates

603.f: Storage of unused equipment

Refer to the "Location" section of this inspection report for additional details.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

UNUSED EQUIPMENT

Comment:

Previous inspection observed various unused equipment stored on the Location. Inspection required Operator to comply with Rule 603.f.

It was observed in this inspection that unused or unneeded equipment has been removed from the Location. This corrective action has been addressed.

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 291568	Type: WELL	API Number: 045-14441	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Previous inspection observed that the "as drilled" coordinates appear incorrect. Operator was required to submit correct "as drilled" latitude and longitude coordinates for the well by 4/28/2020

Operator submitted Form 4 Sundry Doc. #402417767 on 06/10/2020 with the corrected coordinates. Sundry document currently "in process". This corrective action has been addressed.

Corrective Action:

Date:

Facility ID: 291570	Type: WELL	API Number: 045-14440	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

Facility ID: 335211	Type: LOCATION	API Number: -	Status: AC	Insp. Status: RI
---------------------	----------------	---------------	------------	------------------

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696201393	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5172287