

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2020

Submitted Date:

06/12/2020

Document Number:

689804245

FIELD INSPECTION FORM

Loc ID 313194 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10677
Name of Operator: WOLVERINE RESOURCES LLC
Address: 109 EAST 17TH STREET #430
City: CHEYENNE State: WY Zip: 82001

Findings:

- 10 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Reeves, Shane		shane@wolverineresources.com	
		dnr_cogccengineering@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272296	WELL	SI	07/01/2017	GW	081-07184	ANDERSON 43-29	SI

General Comment:

COGCC Inspection Report 689804245 Summary
On Monday 06/01/2020 at approximately 12:50, I, Inspector Emily Waldron, conducted a field inspection at Wolverine Resources LLC Anderson 43-29, at 05-081-07184 in Moffat County Colorado. While there, I observed a shut-in location. The inspection was a follow up inspection to inspection document number 689803165 in response to complaint document number 200447765. No corrective actions appear to have been performed.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery. No wellhead sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/26/2018
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-241-5523		
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT			
Comment:	4 - 2" steel risers not marked for abandonment or LOTO. Flowline risers not LO/TO or marked are considered unused equipment.			
Corrective Action:	Comply with Rule 603.f .	Date:	07/19/2019	
Type	DEBRIS			
Comment:	Trash and debris present on location and beginning to migrate off location.			
Corrective Action:	Comply with Rule 603.f .	Date:	07/29/2019	
Type	STORAGE OF SUPL			
Comment:	Equipment mentioned in previous inspection continues to be stored on location.			
Corrective Action:	Comply with Rule 603.f .	Date:	01/28/2019	
Type	OTHER			
Comment:	Non-reportable spills, stained soil on location.			
Corrective Action:	Comply with Rule 603.f . Control and contain spills/releases and clean up per Rule 906.a. Properly treat or dispose of oily waste in accordance with 907.e.		Date:	07/29/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Deadman # & Marked	#		corrective date
Comment:	Guy line anchors not marked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	08/05/2019

Type: Horizontal Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	#	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 272296 Type: WELL API Number: 081-07184 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports. Last production reported June 2019.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Submit required Form 7(s) to COGCC per rule 309.

Date: 07/19/2019

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689804271	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5173310