

**Inspection Photos**  
**Location Name: Sack #1**  
**Location ID:319867**



**Photo 1 WH**



**Photo 2 Weeds on location and gut line anchor not properly marked**

**Inspection Photos**  
**Location Name: Sack #1**  
**Location ID:319867**



**Photo 3 Weeds on location and gut line anchor not properly marked**



**Photo 4 Weeds on location and gut line anchor not properly marked**

**Inspection Photos**  
**Location Name: Sack #1**  
**Location ID:319867**



**Photo 5 Weeds on location and gut line anchor not properly marked**



**Photo 6 Weeds along road access and deep ruts in road no proper BMP's**

**Inspection Photos**  
**Location Name: Sack #1**  
**Location ID:319867**



**Photo 7 no tracking pad on lease road entrance . Deep ruts on access road no proper BMP's**



**Photo 8 Weeds on location.**

# Inspection Photos Location Name: Sack #1 Location ID:319867



Colorado Oil and Gas Conservation Commission  
 39.98598, -104.95962, 1539.4m  
 Jun 12, 2020 10:41:42

Photo 9 TNK BTRY




Photo 10 meter test card

**Inspection Photos**  
**Location Name: Sack #1**  
**Location ID:319867**



**Photo 11 no tracking pad to entrance to production facility from York street.**



**Photo 12 New 3in line ran from production tank to ECD**