

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/27/2020

Submitted Date:

05/27/2020

Document Number:

699801170

FIELD INSPECTION FORM

Loc ID: 334499 Inspector Name: De Paolo, Corey On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 18 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10433
 Name of Operator: LARAMIE ENERGY LLC
 Address: 1401 SEVENTEENTH STREET #1401
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287345	WELL	SI	02/01/2020	GW	077-09167	WOODS-SPANGLER 15-11	SI
287346	WELL	PR	06/24/2008	GW	077-09166	WOODS-SPANGLER 15-12	PR
287347	WELL	PR	03/01/2017	GW	077-09165	WOODS-SPANGLER 15-13	PR
287348	WELL	PR	12/11/2007	GW	077-09164	WOODS-SPANGLER 15-14	PR
287349	WELL	PR	04/26/2007	GW	077-09163	WOODS-SPANGLER 21-1	PR
287350	WELL	PR	10/20/2010	GW	077-09162	WOODS-SPANGLER 22-4	PR
288356	WELL	PR	12/29/2007	GW	077-09214	WOODS-SPANGLER 16-16	PR

General Comment:

[COGCC Inspection Report Summary](#)
 On Wednesday 5/27/20 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at LARAMIE ENERGY LLC Woods Spangler /15-13 Pad, Location #334499 in Mesa County Colorado.
 Refer to document #699800778 inspection conducted on 3/24/20. Not all previous corrective actions have been completed. While there, I observed normal production operations.
 During this inspection the following possible compliance issues were observed: Unused pipe stored on North end of location. See photo #0815 and #1264 with a previous corrective action date of 2/29/20. Unused equipment by wellhead. See photo #1266 with a corrective action date of 8/27/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text" value="911"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment by wellhead. See photo #1266		
Corrective Action:	production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused equipment from location.		Date: <u>08/27/2020</u>
Type	STORAGE OF SUPL		
Comment:	Unused pipe stored on North end of location. See photo #0815 and #1264		
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused pipe from location.		Date: <u>02/29/2020</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:			Date:

Type	LOCATION		
Comment:	Barbed wire fence around location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:	500 gallon capacity				
Corrective Action:					Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment: Separate containment							
Corrective Action:					Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	4	300 BBLs	STEEL AST		,		
Comment:							
Corrective Action:					Date:		
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment: Centralized containment							
Corrective Action:					Date:		
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 287345 Type: WELL API Number: 077-09167 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: Last produced January 2020
 Corrective Action: _____ Date: _____

Facility ID: 287346 Type: WELL API Number: 077-09166 Status: PR Insp. Status: PR

Producing Well

Comment: Producing
 Corrective Action: _____ Date: _____

Facility ID: 287347 Type: WELL API Number: 077-09165 Status: PR Insp. Status: PR

Producing Well

Comment: Producing
 Corrective Action: _____ Date: _____

Facility ID: 287348 Type: WELL API Number: 077-09164 Status: PR Insp. Status: PR

Producing Well

Comment: Producing
 Corrective Action: _____ Date: _____

Facility ID: 287349 Type: WELL API Number: 077-09163 Status: PR Insp. Status: PR

Producing Well

Comment: Producing
 Corrective Action: _____ Date: _____

Facility ID: 287350 Type: WELL API Number: 077-09162 Status: PR Insp. Status: PR

Producing Well

Comment: Producing
 Corrective Action: _____ Date: _____

Facility ID: 288356 Type: WELL API Number: 077-09214 Status: PR Insp. Status: PR

Producing Well

Comment: Producing
 Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gravel						
		Ditches				
		Compaction				
Ditches						
Compaction						
		Culverts				
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402407424	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5160463
699801171	Photos for Insp. #699801170	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5160459