

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/12/2020

Submitted Date:

06/12/2020

Document Number:

699801264

FIELD INSPECTION FORM
 Loc ID 334149 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293213	WELL	PR	03/17/2009	GW	077-09447	ORCHARD UNIT 10-14 (J10OUB)	PR
293215	WELL	PR	03/18/2009	GW	077-09448	ORCHARD UNIT 10-11 (J10OUB)	PR
298383	WELL	PR	04/30/2009	GW	077-09754	ORCHARD UNIT 10-11H (J10OUB)	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 6/12/20 at approximately 10:30 hours, I, Inspector Corey De Paolo,
Conducted a follow up inspection at CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /10NWSE,
Location #334149 in Mesa County Colorado.

Refer to document #699801130 inspection conducted on 5/19/20. Not all corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Multiple unmarked deadman. See photo #1222, #1353,
#1223 and #1354 with a previous corrective action date of 6/2/20.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 2	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 2	
Comment:	Multiple unmarked deadman. See photo #1222, #1353, #1223 and #1354.	
Corrective Action:	All guy line anchors left buried for future use shall be identified by a marker of bright color not less than four (4) feet in height. Properly mark deadman.	Date: 06/02/2020
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 3	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Centralized containment		
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 293213	Type: WELL	API Number: 077-09447	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:			Date:	
Facility ID: 293215	Type: WELL	API Number: 077-09448	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:			Date:	
Facility ID: 298383	Type: WELL	API Number: 077-09754	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts				
Sediment Traps						
Gravel						
Berms						
Ditches						
		Berms				
		Waddles				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801265	Photos for Insp. #699801264	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5174267