

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2020

Submitted Date:

06/15/2020

Document Number:

693502983**FIELD INSPECTION FORM**

Loc ID 320506 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:

**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa,	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271836	WELL	PR	03/01/2020	OW	001-09493	IVEY 16-11	PR

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,

Comment: Tanks are rusted , pitted, or peeling paint, or show evidence of inadequate repair.

Corrective Action: Inspect, maintain and repair tanks following standard industry practice such as API 12R. Rule 605 a (1)

Date: 12/06/2019

**Paint**

Condition Inadequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: Corrective Action: Date: **Venting:**

Yes/No NO

Comment: Corrective Action: Date: **Flaring:**

Type		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 271836 Type: WELL API Number: 001-09493 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday June 15, 2020 at approximately 9:29AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Ivey #16-11</p> <p>Operator: KP Kauffman</p> <p>API#: 05-001-09493</p> <p>County: Adams</p> <p>While there, I observed a well site and production site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Tank conditions: Rule 605 a (1) Corrective action date of 12-6-19 See photos</p> <p>This is a follow up inspection per doc #693501697. At time of inspection I observed what appeared to spray paint on some spots on production tank. Tank paint is still chipping were spray paint was applied. Multiple area's still in need of repair</p> <p>Weather conditions: clear and location dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	06/15/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693502984	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5174535">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5174535</a>