

**Inspection Photos**  
**Operator: Catamount Energy**  
**API#: 067-07336**  
**Date: 6/11/2020**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing on cobbles, although weedy, with irrigated pasture grasses and yellow sweetclover.



Photo 3. View of jointed goatgrass (approx. 300) and Canada thistles (approx. 75), two noxious weeds that need to be treated within the southern project area.



Photo 4. View of the northern project area from the northwestern corner facing eastward. Revegetation is irrigated and appears to be progressing similar to the reference area.



Photo 5. View of reference area comprised of irrigated field, with grasses such as orchard grass, tall fescue, and forbs such as yellow sweetclover.