

Inspection Photos

Operator: Merrion Oil and Gas
API: 067-06119
Date: 6/11/2020



Photo 1. View of the project area from the northwestern corner facing southeastward. Revegetation within the western project area is approximately the same as surrounding reference area.



Photo 2. View of the project area from the southeastern corner facing northwestward. Revegetation in the eastern portion is more sparse than western project area, but appears to be approaching reclamation 80 percent of reference area standard.



Photo 3. View of the project area from the southern edge facing northward. Revegetation is progressing with grasses and forbs similar to the reference area, irrigated field, with orchard grass, alfalfa, and yellow sweetclover.



Photo 4. View of reference area comprised of irrigated field, with grasses such as orchard grass, tall fescue, and forbs such as yellow sweetclover.