

# Inspection Photos

API: 05-055-06037

Operator: OXY USA INC

Inspection Date: 6/9/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-055-06037 | Date: 6/9/2020

## Inspection Photos



**Photo 1.** Facing toward the sharp turn in the road near the location. Noxious weeds were controlled in this area and are much less present. There are a few noxious weeds beginning to emerge so a follow up weed control should be performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/9/2020



## Inspection Photos



**Photo 2.** Facing east toward the location. A pile of rock debris is stored at the location and will need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/9/2020

## Inspection Photos



**Photo 3.** Well sign has been updated to reflect the current operator.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/9/2020



## Inspection Photos



**Photo 4.** Noxious weed control was performed in this area last fall which appears to have been effective.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/9/2020



## Inspection Photos



**Photo 5.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06037 | Date: 6/9/2020