

Inspection Photos

API: 05-055-06316

Operator: OXY USA INC

Inspection Date: 6/9/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06316 | Date: 6/9/2020

Inspection Photos



Photo 1. Facing south ascending the hill toward the location. The BMP's along the side of the road are not maintained. Red arrow points to rock wattle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06316 | Date: 6/9/2020

Inspection Photos



Photo 2. Facing southwest toward the location. Operator sign has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06316 | Date: 6/9/2020

Inspection Photos



Photo 3. Facing northeast along the hill side at the location. Noxious weed control was performed in this area last fall which appears to have been effective.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06316 | Date: 6/9/2020

Inspection Photos



Photo 4. Facing northeast toward the location from at the top cut slope. There is some noxious weeds present in this area which needs to be controlled to prevent spreading.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06316 | Date: 6/9/2020

Inspection Photos



Photo 5. Facing southwest toward the location. Vegetation is well established in the interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06316 | Date: 6/9/2020