

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2020

Submitted Date:

06/15/2020

Document Number:

696103123**FIELD INSPECTION FORM**Loc ID 332241 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nbl energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271336	WELL	PA	10/09/2017	OW	123-22025	EISENSTAT 22-21	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Abandoned. ALL equipment removed.
 Reclamation progressing.
 Abandoned Battery SE corner GPS coordinates: 40.477430, -104.536450

Abandoned Centralized Battery formerly served 5 Location IDs (332510, 331064, 332241, 332242, 319496).
 (Well(s): 1: Temporarily Abandoned | TA ; 4: Plugged & Abandoned | PA).

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

0

Comment: [Plugged & Abandoned | PA. BATTERY Abandoned.](#)
[ALL Equipment removed.](#)Corrective Action: Date:

Type: Horizontal Heated Separator

0

Comment: [Plugged & Abandoned | PA. BATTERY Abandoned.](#)
[ALL Equipment removed.](#)Corrective Action: Date:

Type: Plunger Lift

0

Comment: [Plugged & Abandoned | PA. BATTERY Abandoned.](#)
[ALL Equipment removed.](#)Corrective Action: Date:

Type: Gas Meter Run

0

Comment: [Plugged & Abandoned | PA. BATTERY Abandoned.](#)
[ALL Equipment removed.](#)Corrective Action: Date:

Type: Ancillary equipment

0

Comment: [Plugged & Abandoned | PA. BATTERY Abandoned.](#)
[ALL Equipment removed.](#)Corrective Action: Date: **Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected Facilities

Facility ID: 271336 Type: WELL API Number: 123-22025 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 06/15/2020 at approximately 11:38 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: EISENSTAT-66N64W /22NENW Location ID: 332241 Well Name: Eisenstat 22-21 API: 05-123-22025 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.477430, -104.536450</p> <p>Abandoned Centralized Battery formerly served 5 Location IDs (332510, 331064, 332241, 332242, 319496). (Well(s): 1: Temporarily Abandoned TA ; 4: Plugged & Abandoned PA).</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #401227325 indicates plugging, cut/cap date: 01/18/2017. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103124	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5175762