

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2020

Submitted Date:

06/16/2020

Document Number:

693802097

**FIELD INSPECTION FORM**

Loc ID 315260 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: 110 W 7TH STREET  
City: FORT WORTH State: TX Zip: 76102

**Contact Information:**

| Contact Name     | Phone          | Email                         | Comment                         |
|------------------|----------------|-------------------------------|---------------------------------|
| Labowskie, Steve |                | steve.labowskie@state.co.us   |                                 |
| Dooling, Jessica | (970) 878-6800 | Jessica_Dooling@xtoenergy.com | Piceance Basin Field            |
| Koehler, Bob     |                | bob.koehler@state.co.us       |                                 |
| Browning, Chuck  | 970-433-4139   | chuck.browning@state.co.us    | Field Inspector                 |
| West, Jerry      |                | Jerry_west@xtoenergy.com      | Production Superintendent       |
| Clark, Erin      | 405-319-3250   | Erin_clark@xtoenergy.com      | XTO Piceance and BOPCO Piceance |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 230514      | WELL | IJ     | 04/01/2019  | DSPW       | 103-08181 | U S A PICEANCE CREEK T73-11G | AC          |

**General Comment:**

Routine UIC inspection. Injection well inspection only.

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Main   |  |       |
| comment:           |        |  |       |
| Corrective Action  |        |  | Date: |
| Type               | Access |  |       |
| comment:           |        |  |       |
| Corrective Action  |        |  | Date: |

Overall Good:

|                      |                           |  |       |
|----------------------|---------------------------|--|-------|
| <b>Signs/Marker:</b> |                           |  |       |
| Type                 | WELLHEAD                  |  |       |
| Comment:             | Sign at location entrance |  |       |
| Corrective Action:   |                           |  | Date: |

|                           |                     |  |             |
|---------------------------|---------------------|--|-------------|
| Emergency Contact Number: |                     |  |             |
| Comment:                  | 970-675-4117 or 911 |  |             |
| Corrective Action:        |                     |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

|                          |     |  |                 |
|--------------------------|-----|--|-----------------|
| <b>Equipment:</b>        |     |  | corrective date |
| Type: Deadman # & Marked | # 4 |  |                 |
| Comment:                 |     |  |                 |
| Corrective Action:       |     |  | Date:           |
| Type: Bradenhead         | # 1 |  |                 |
| Comment:                 |     |  |                 |
| Corrective Action:       |     |  | Date:           |

|                    |    |  |       |
|--------------------|----|--|-------|
| <b>Venting:</b>    |    |  |       |
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Flaring:</b>    |  |  |       |
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**

Facility ID: 230514 Type: WELL API Number: 103-08181 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg 160 Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
(e.g. 30 psig or -30" Hg) Inj Zone: WSTCA  
TC: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ Last MIT: 04/28/2016  
Brhd: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Routine UIC inspection. Active injection at time of inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 693802098    | Inspection photos 6/15/2020 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5176874">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5176874</a> |