

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2020

Submitted Date:

06/16/2020

Document Number:

693802107

FIELD INSPECTION FORM

Loc ID 315154 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 21459 CR 5
City: RIFLE State: CO Zip: 81650

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
West, Jerry		Jerry_west@xtoenergy.com	Production Superintendent
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Clark, Erin	405-319-3250	Erin_clark@xtoenergy.comgy.com	XTO Piceance and BOPCO Piceance
Koehler, Bob		bob.koehler@state.co.us	
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230336	WELL	TA	12/05/2017	DSPW	103-07996	U S A-PICEANCE CREEK T63-12G	TA

General Comment:

[Routine UIC inspection. Injection well inspection only.](#)

Location			
Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign at location entrance		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-675-4117 or 911		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 230336 Type: WELL API Number: 103-07996 Status: TA Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>0</u> (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	Inj Zone: <u>WSTCA</u>
Brhd:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	Last MIT: <u>06/29/2015</u>
			AnnMTReq: _____

Comment: Routine UIC Inspection. Well temporarily abandoned.
MIT scheduled for 6/26/2020. Form42 Doc#402410192 submitted 6/1/2020.

Corrective Action: Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693802108	Inspection photos 6/15/2020	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5176879