

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/16/2020

Submitted Date:
06/16/2020

Document Number:
699601252

FIELD INSPECTION FORM

Loc ID 312141 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 35190
Name of Operator: GRAYHORSE OPERATING INC
Address: 20 EAST 5TH ST STE 320
City: TULSA State: OK Zip: 74103

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		kyancey@grayhorse.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218838	WELL	PR	03/01/2020	OW	075-05599	WRITEBOL 3	PR

General Comment:

Follow-up FIR from Doc3680305887. Correspondance with Mr. C. Ellis (Greyhorse) indicated Rob Young (COGCC) approved the CA's cited for spill-excavation/removal of affected soils-repair berm and return well to service. On-site FIR observations show spill has been cleaned-up - waste material is removed - berms have been repaired - well has returned to service. No data base record of approval from COGCC to return well to service was found during this FIR. Contact COGCC Environmental Specialist (Rob Young) with any questions or concerns.

Location			
Lease Road:			
Type	Access		
comment:	Two track cropland		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	Spill cited/documented in Doc# 689305887 based on surface physical observations has been remediated - repaired and returned well to service. Contact COGCC Environmental (Rob Young) with any questions/concerns.		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 0		corrective date
Comment:	No change in equipment inventoried.		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 218838 Type: WELL API Number: 075-05599 Status: PR Insp. Status: PR

Producing Well

Comment: OW

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Located within dryland cropland w/rotational tillage](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Follow-up FIR Doc#680305887 - Satisfactory	schureky	06/16/2020