

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment

1

corrective date

Comment: electric

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 240129 Type: WELL API Number: 123-07917 Status: PR Insp. Status: PR

Producing Well

| | | |
|--------------------|----|-------|
| Comment: | PR | |
| Corrective Action: | | Date: |

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were sunny and windy. | medinaj | 06/16/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 699501469 | pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5177875 |