

Inspection Photos
Operator: BP America
API: 067-07632
Date: 6/16/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing here with western wheatgrass, sand dropseed, and rubber rabbitbrush.

Russian knapweeds



Treated musk thistles



Photos 3/4. View of the weeds within the project area. Russian knapweeds on the left are not treated. Musk thistles on the right appear to be treated.



Photo 5. View of the western project area, facing northward. Equipment stored in this portion of the project area.



Photo 6. View of the northwestern cut-slope , needs further stabilization.



Photo 6. View of the reference area, comprised of pinyon and juniper woodland with understory of grasses and forbs such as western wheatgrass, blue grama, prickly pear, as well as shrubby gambel oak.