

Inspection Photos
Operator: BP America
API: 067-07620
Date: 6/16/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing, although sparse, with western wheatgrass, crested wheatgrass, and sand dropseed.



Photo 3. View of Russian thistle debris and plastic debris on fence and near fired equipment.



Photo 4. View of more Russian thistle debris at fenceline, needs to be removed and properly disposed of.



Photo 5. View of musk thistles along the access road that appear to be treated with herbicide recently.



Photo 6. View of the reference area, comprised of pinyon and juniper woodland with understory of grasses and forbs such as western wheatgrass, blue grama, prickly pear, as well as shrubby gambel oak.