

**Inspection Photos**  
**Operator: Southland Royalty**  
**API: 067-08654**  
**Date: 6/16/2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Aggressive musk thistle removal was recently conducted. Thousands of individuals appear treated. Revegetation is needed to stabilize treatment areas and promote desirable vegetation.



Photo 3. View of the western project area from the northwestern corner facing southward. Revegetation is progressing here with western wheatgrass, crested wheatgrass, and smooth brome.



Photo 4. View of musk thistle rosettes within the project area.



Photo 5. View of the reference area, comprised of open grass field with grasses such as western wheatgrass, Indian ricegrass, and smooth brome.