

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2020

Submitted Date:

06/18/2020

Document Number:

700900164

FIELD INSPECTION FORMLoc ID 320322 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 76859

Name of Operator: SCHREIDER & COMPANY INC

Address: 9227 E LINCOLN AVE SUITE 200

City: LONE TREE State: CO Zip: 80124

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schneider, Jeff	970-867-9437/ (214) 244-3819	jeff@schneiderenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203446	WELL	SI	01/01/2018	GW	001-09005	GRETCHEN RAGLUND 2-14	PA

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Flowline risers not LO/TO		
Corrective Action:	Flowline risers not LO/TO or marked are considered unused equipment per Rule 603.f. For unused or unmarked flowline risers 24hrs to lock out tag out. Corrective Action Date 7/17/2020 to remove riser. See attached photos # 3.	Date:	07/17/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused (pipe) equipment on the ground.		
Corrective Action:	Unused equipment (pipe) . Per rule 603.f. See attached photo #1 & 2, Corrective Action Date 9/17/2020.	Date:	09/17/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203446 Type: WELL API Number: 001-09005 Status: SI Insp. Status: PA

Completion

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday June 12, 2020 at approximately 11:15am. I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Gretchen Ragland #2-14, Schreider and Company INC at API # 001-09005 in Adams County Colorado.</p> <p>While there, I observed a well that in in progress of being Plugged and abandoned. During this inspection the following possible compliance issues were observed: Unused (pipe) equipment on the ground. Unused equipment (pipe) . Per rule 603.f. See attached photo #1 & 2, Corrective Action Date 9/17/2020.</p> <p>Flowline risers not LO/TO or marked are considered unused equipment per Rule 603.f. For unused or unmarked flowline risers 24hrs to lock out tag out. Corrective Action Date 7/17/2020 to remove riser. See attached photos # 3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	06/18/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900165	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5179024