

# Final Reclamation Inspection

June 16, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 319865

Inspection Document #: 697501653

Adams County, CO

SWSE Section 20 T1S R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 1.** Photo taken from the northern access road, facing West. Photo illustrates the Operator attempted to conduct final reclamation activities; however, the establishment of desirable plant species was not uniform throughout. Patches of weedy, undesirable annuals (mostly Kochia) were observed along the access road and well location.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 2.** Photo taken from the northern access road, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 3.** Photo taken along a portion of the access road, facing West. Photo illustrates little germination of desirable plant species with the establishment of Kochia.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 4.** Photo taken along a portion of the access road, facing South. See comments under Photo 3.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 5.** Photo taken along a portion of the access road, facing West. Photo illustrates a culvert has not been removed. There appears to be an old irrigation ditch.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 6.** Photo taken along a portion of the access road, facing West. This is a second culvert left just south of the previous.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 7.** Photo taken from the southern access road, facing South. Photo illustrates the establishment of desirable species but lacks uniform establishment with bare patches.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 8.** Photo taken from the northern well location, facing South. Photo illustrates vegetative growth of wheat that appears to have established from the mulch. There was some desirable plant species establishment but not uniform.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 9.** Photo taken from the northwestern well location, facing Southeast. See comments under Photo 8.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 10.** Photo taken from a portion of the well location. Photo illustrates the establishment of Scotch thistle, a List B CO Noxious weed. No Scotch thistle was observed flowering, only some Musk.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 11.** Photo taken from a portion of the well location. Photo illustrates the establishment of Musk thistle, a List B CO Noxious weed. Musk thistle has appeared to just start flowering.

Inspection Photos  
Location Name: AYLOR #2  
Location ID: 319865



**Photo 12.** Reference photo taken along a portion of the northern access road, facing North.