

FORM
INSPRev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2020

Submitted Date:

06/12/2020

Document Number:

693502975

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
320295 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 46290 _____
Name of Operator: KP KAUFFMAN COMPANY INC _____
Address: 1675 BROADWAY, STE 2800 _____
City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80202 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 _____ Number of Comments
2 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Lara-Mesa,	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203386	WELL	PR	02/01/2019	OW	001-08895	SACK G UNIT 1	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date:
Corrective Action:			

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds on location and around separator		
Corrective Action:	Comply with 603 f	Date:	08/12/2020

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barb wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Barb wire		
Corrective Action:		Date:	

Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	#		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:	Tanks are rusted , pitted, or peeling paint, or show evidence of inadequate repair.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date:	08/12/2020

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	48bbbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shares containment with crude oil tank	
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203386 Type: WELL API Number: 001-08895 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday June 12, 2020 at approximately 10:23, I, Inspector Randy Silver, conducted an on-site inspection. Location: Sack G Unit #1 Operator: KP Kauffman API#: 05-001-08895 County: Adams While there, I observed well site and production facility During this inspection the following possible compliance issues were observed: Weeds: Rule 603 f Corrective action date of 8-12-20 see photo 2 Tank maintenance: rule 605 a (1) Corrective action date 8-12-20 see photo 3 Weather conditions: Clear and location dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	06/12/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402420760	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5173413
693502976	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5173400