

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2020

Submitted Date:

06/20/2020

Document Number:

700402033

FIELD INSPECTION FORM

Loc ID 335790 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|---|--|
| Elsenser, Garrett | 720-880-6340 | cogcc.inspections@caerusoila ndgas.com | All Piceance inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------------|-------------|
| 273668 | WELL | PR | 10/30/2005 | GW | 103-10482 | FIGURE FOUR UNIT 8013D MO1 498 | PR |
| 273669 | WELL | PR | 10/18/2005 | GW | 103-10484 | FIGURE FOUR UNIT 8014D MO1 498 | PR |
| 273670 | WELL | PR | 10/30/2005 | GW | 103-10483 | FIGURE FOUR UNIT 8012D M01 498 | PR |

General Comment:

On 6-18-2020 inspector Rick Moran conducted a follow up inspection at Caerus well pad 8013D M01 in Rio Blanco county of FIR document 700401704.

The following compliance issues were resolved:
1) Containers received new labels.

This is a summary of inspection report 700402033.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| Type: | | | corrective date |
|---------------------|----------------------|-------|-----------------|
| Other | # 2 | | |
| Comment: | Equipment buildings. | | |
| Corrective Action: | | Date: | |
| Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Bird Protectors | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Ancillary equipment | # 2 | | |

| | | |
|---|-----|-------|
| Comment: Chemical containers. | | Date: |
| Corrective Action: | | Date: |
| Type: Deadman # & Marked | # 8 | |
| Comment: | | Date: |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 2 | |
| Comment: | | Date: |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| | | Date: | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | Date: | | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| | | Date: | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | Date: | | |

Venting:

| | | |
|--------|----|--|
| Yes/No | NO | |
|--------|----|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 273668 Type: WELL API Number: 103-10482 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 273669 Type: WELL API Number: 103-10484 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 273670 Type: WELL API Number: 103-10483 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction | Pass | | | | | |
| Berms | Pass | | | Material Handling And Spill Prevention | Pass | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 700402034 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180165 |