



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Taiga Fed 7F-21-4-102

API: 05-103-08086

Inspection: 700402056



39 68943, -108.854, 6930.9ft, 176°
06/19/2020 12:59:12 PM



39.68895, -108.854, 6927.1ft, 310°
06/19/2020 12:57:14 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Flow line valve.

Taiga Fed 7F-21-4-102

API: 05-103-08086

Inspection: 700402056



39.6892, -108.85383, 6933.7ft, 133°
06/19/2020 12:56:29 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Bermed area.

Taiga Fed 7F-21-4-102

API: 05-103-08086

Inspection: 700402056



39.68905, -108.85401, 6926.6ft, 68°
06/19/2020 12:57:36 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Concrete chunks.

Taiga Fed 7F-21-4-102

API: 05-103-08086

Inspection: 700402056

