

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: 4' barb wire around production equipment / fabricated tubing around wellhead

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date: _____

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date: _____

Type: Bird Protectors

1

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment

1

Comment: automation

Corrective Action:

Date: _____

Type: Bradenhead

1

Comment:

Corrective Action:

Date: _____

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date: _____

Type: Plunger Lift

1

Comment:

Corrective Action:

Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	

CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: shares containment with oil tanks				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 202975 Type: WELL API Number: 001-08381 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>This is a follow up inspection for the Extraction Bankruptcy This is a follow up inspection for document # 687400759, corrective actions from previous inspection appear to have been addressed. At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were sunny and light wind.</p>	medinaj	06/18/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501479	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5181221