

Inspection Photos
Operator: BP America
API: 067-08991
Date: 6/19/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing westward. Revegetation is progressing, largely with smooth brome and western wheatgrass.



Photo 3. View of the northeastern fill slope from the northeastern corner facing westward.



Photo 4. View of erosional channel forming downstream of northeastern diversion, approximately 2 feet wide and 1 foot deep.



Photo 5. View of the reference area, comprised of ponderosa pine woodland with a grassy understory of smooth brome and western wheatgrass, as well as gambel oaks.