

Inspection Photos

API# 009-06189

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 6/22/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06189 | Date: 6/22/2020

Inspection Photos



Photo 1. Facing west toward the PW tank and meter shed located adjacent to CR-49 and 575' east of the well. No operator sign is visible from the county road but a sign was observed on backside of tank. Meter shed still appears to be unstable and there is no berm around the tank. Corrective actions were not completed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06189 | Date: 6/22/2020

Inspection Photos



Photo 2. The meter shed is not maintained and remains unstable. Erosion has occurred underneath the meter shed which is a safety concern..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/22/2020

Inspection Photos



Photo 3. Corrective actions of the previous inspection were not performed. There is no berm around the 200 bbls tank. There is unused equipment at the location (red arrow).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/22/2020

Inspection Photos



Photo 4. The tank sign and NFPA label are installed on backside of the tank which is not readily visible from the front side along the county road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/22/2020

Inspection Photos



Photo 5. Facing southwest toward the wellsite. There is metal tin debris from the wellsite observed northeast of the well (red arrow).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/22/2020

Inspection Photos



Photo 6. Facing east at the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/22/2020

Inspection Photos




Photo 7. Facing northeast toward the well. The gate is lying on the ground and the fence around the well is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/22/2020

Inspection Photos



Photo 8. There are pieces of metal debris laying next to the pumpjack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/22/2020