

Inspection Photos

Operator: BP America
API: 067-07138
Date: 6/19/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing, largely with smooth brome and western wheatgrass.



Photo 3. View of the eastern fill slope from the southeastern corner facing northward.



Photo 4. View of the northern cut slope from the northeastern corner facing westward. Stabilization measures are needed on the well pad cut-slope.



Photo 5. View of the reference area, comprised of ponderosa pine forest with a gambel oak, Sandberg bluegrass, and penstemon.