

Inspection Photos

ID# 441082

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 6/22/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID# 441082 | Date: 6/22/2020

Inspection Photos



Photo 1. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 6/22/2020

Inspection Photos



Photo 2. Facing north toward the location. Soils are compacted and the location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 6/22/2020

Inspection Photos



Photo 3. Facing north at southeast side of the location. Sign is posted near the pipeline.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 6/22/2020

Inspection Photos



Photo 4. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 6/22/2020

Inspection Photos



Photo 5. Facing northwest at the location. The location has not been reclaimed and soils are compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 6/22/2020

Inspection Photos



Photo 6. Facing northwest. The piles of soil, gravel/debris remains at the northwest corner of the location (red arrow). There appears to be cement in this area shown in circled area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 6/22/2020