

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2020

Submitted Date:

06/24/2020

Document Number:

700900191**FIELD INSPECTION FORM**Loc ID 319664 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10711Name of Operator: PAINTED PEGASUS PETROLEUM LLCAddress: 16820 BARKER SPRINGS RD #521City: HOUSTON State: TX Zip: 77084**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TROY	713) 818-8152	tmouret@p3petro.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	
Huck, Keith		khuck@adcogov.org	Adams County Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200774	WELL	PR	11/01/2019	GW	001-06177	RANDALL 41-10	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds.		
Corrective Action:	Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/10/2020. See attached photos #.3 through 10	Date:	07/10/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	
Condensate	Tank	<= 1 bbl	
Comment:	Mechanical Conditions (Condensate tank leaking)		
Corrective Action:	Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 30 days unless leak is found. Immediate call to operator if leak is found and 24 hours (6/25/2020) to fix the leak or isolate leak. See attached photos #. 2 & 3.		Date: 06/25/2020

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:	Building(s) in disrepair.		
Corrective Action:	Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Corrective Action Date 7/27/2020 See attached photos #.5 through 9.		Date: 07/27/2020

Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		39.984885,-104.530447
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 200774 Type: WELL API Number: 001-06177 Status: PR Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

BradenHead

Comment: Appears to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday June 24, 2020 at approximately 9:57Am, I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Randall 41-10 tank Battery Painted Pegasus Petroleum at API #001-06177 in Adams County Colorado.</p> <p>While there, I observed a Temporarily Abandoned Well,</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Mechanical Conditions (Condensate tank leaking), inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 30 days unless leak is found. Immediate call to operator if leak is found and 24 hours (6/25/2020) to fix the leak or isolate leak. See attached photos #. 2 & 3.</p> <p>Building(s) in disrepair. Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Corrective Action Date 7/27/2020See attached photos #.5 through 9.</p> <p>Weeds. Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/10/2020. See attached photos #.3 through 10</p> <p>I left a message with Troy Mouret with Painted Pegasus Petroleum explaining that there is an active leak at this location (API # 001-06177) on a condensate tank and I have herd nothing back from Troy or any one regarding the situation.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	06/24/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900192	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5182975