

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2020

Submitted Date:

06/24/2020

Document Number:

700700947

FIELD INSPECTION FORM

 Loc ID 334692 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: PO BOX 370
 City: PARACHUTE State: CO Zip: 81635
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:
 13 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
, COGCC		michael.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210866	WELL	PR	08/12/1997	GW	045-06624	UNION GV 14-2	PR
285450	WELL	SI	03/01/2020	GW	045-12488	SOLVAY GM 542-2	PR
285451	WELL	PR	06/30/2006	GW	045-12489	SOLVAY GM 442-2	PR
285453	WELL	PR	06/30/2006	GW	045-12490	SOLVAY GM 441-2	PR

General Comment:[COGCC Inspection Report Summary](#)

On Wednesday 6/24/20 at approximately 11:00 AM, I, Inspector Scott Ramsey, conducted an inspection on site in response of Complaints 18200448946, 18200448939, 18200448940 at TEP GM 14-2, at Location # 334692 in Garfield Colorado.

While there, I observed normal production operations. No evidence of odor. Winds are calm.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	methanol tank next to seperator		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:	shared containment with condensate tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	210866	Type:	WELL	API Number:	045-06624	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing							Date:	
Corrective Action:								Date:	
Complaint									
Comment:	Complaints 18200448946, 18200448939, 18200448940							Date:	
Corrective Action:								Date:	
Facility ID:	285450	Type:	WELL	API Number:	045-12488	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	producing							Date:	
Corrective Action:								Date:	
Complaint									
Comment:	Complaints 18200448946, 18200448939, 18200448940							Date:	
Corrective Action:								Date:	
Facility ID:	285451	Type:	WELL	API Number:	045-12489	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing							Date:	
Corrective Action:								Date:	
Complaint									
Comment:	Complaints 18200448946, 18200448939, 18200448940							Date:	
Corrective Action:								Date:	
Facility ID:	285453	Type:	WELL	API Number:	045-12490	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing							Date:	
Corrective Action:								Date:	
Complaint									
Comment:	Complaints 18200448946, 18200448939, 18200448940							Date:	
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
Gravel		Gravel				
Culverts		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700956	photos for GM 14-2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5183218