

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2020

Submitted Date:

06/24/2020

Document Number:

699301994**FIELD INSPECTION FORM**Loc ID 306548 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289677	WELL	TA	03/12/2019	OW	123-24893	CANNON-USX W 15-8	TA

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	shares fencing with Ignitor/Combustor		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas Meter Run has fabricated square tubing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	automation		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Card in meter house indicates that calibration is current through 7-23-2020		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	on pallet to reinstall during return to service		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	shares containment with crude tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					

Paint

Inspector Name: Revas, Robbie

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 289677 Type: WELL API Number: 123-24893 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA since 3-12-2019 Form 21 (MIT) Doc # 401950663 submitted on 2-25-2019, Form 4 (TA) Doc # 402317603 Submitted 2-19-2020 and are approved.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 6/24/2020 at approximately 1220 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Cannon USX W 15-8 at API # 05-123-24893 in Weld County Colorado.</p> <p>While there, I observed wellsite and tank battery, TA since 3-12-2019 Form 21 (MIT) Doc # 401950663 submitted on 2-25-2019, Form 4 (TA) Doc # 402317603 Submitted 2-19-2020 and are approved.</p> <p>During this inspection no compliance issues were observed: See attached photos. Location is dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	06/24/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301995	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5183277