

Inspection Photos
Operator: BP America
API: 067-09188
Date: 6/24/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass in a grazed condition. Approximately 200 musk thistles observed.



Photo 3. View of the northern project area facing westward.



Photo 4. View of the reference area, comprised of irrigated pasture.