

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 1: LOCATION



PHOTO 2: TANK BATTERY



Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 3: TANK BATTERY



PHOTO 4: WELLHEAD AND SIGN



Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 5: CARPORT STYLE BUILDING ON SOUTH EDGE OF LOCATION.



PHOTO 6: UNUSED RISERS NEAR WEST ENTRANCE OF CARPORT STYLE BUILDING. REMOVE UNUSED RISERS COMPLY WITH NTO AND RULE 603.f.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 7: UNUSED RISERS ON INSIDE CARPORT STYLE BUILDING CLOSE TO NORTH WALL. REMOVE UNUSED RISERS COMPLY WITH NTO AND RULE 603.f.



PHOTO 8: UNUSED RISERS ON INSIDE CARPORT STYLE BUILDING CLOSE TO SOUTHEAST WALL. IT APPEARS THAT THIS RISER IS DISCONNECTED JUST OUTSIDE OF BUILDING ON EAST SIDE. REMOVE UNUSED RISERS COMPLY WITH NTO AND RULE 603.f.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



**PHOTO 9: UNUSED EQUIPMENT STORED INSIDE CARPORT
STYLE BUILDING. LABEL WAS NOT LEGIBLE. REMOVE
UNUSED EQUIPMENT COMPLY WITH RULE 603.f.**



**PHOTO 10: BATTERY OF 55 GALEN BARRELS WEST OF
CARPORT STYLE BUILDING. REMOVE UNUSED EQUIPMENT
COMPLY WITH RULE 603.f.**



Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 11: LABEL ON 5 GAL. BUCKET INCLUDED WITH WEST 55 GAL. DRUM BATTERY.



PHOTO 12: LABEL ON 1 OF THE 55 GAL. DRUMS IN WEST BATTERY.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 13: FLUID ON TOP OF 1 OF THE 55 GAL. DRUMS IN WEST BATTERY. CAN NOT DETERMINE SOURCE OF FLUID AT TIME OF INSPECTION.



PHOTO 14: LABEL ON 55 GAL. DRUM IN WEST BATTERY.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 15: MANUFACTURER LABEL ON 1 OF THE 55 GAL. DRUMS IN WEST BATTERY.



PHOTO 16: MANUFACTURER LABEL ON 1 OF THE 55 GAL. DRUMS IN WEST BATTERY.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 17: METER HOUSE AND GARAGE STYLE BUILDING IN THE MIDDLE OF LOCATION CLOSE TO EAST EDGE.



PHOTO 18: 2" LINE RUNNING FROM SEPARATOR BETWEEN WELLHEAD AND METER HOUSE ON WEST SIDE OF GARAGE STYLE BUILDING.



Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



**PHOTO 19: UNUSED EQUIPEMNT STORED ON PALLET ON
METER HOUSE SKID. REMOVE UNUSED EQUIPMENT COMPLY
WITH RULE 603.f.**



PHOTO 20: INSIDE METER HOUSE.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



**PHOTO 21: UNUSED RISER NEAR METER HOUSE. REMOVE
UNUSED RISERS COMPLY WITH NTO AND RULE 603.f.**



**PHOTO 22: APPEARS TO BE A SEPARATOR BETWEEN
WELLHEAD AND METER HOUSE.**

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 23: UNUSED EQUIPMENT STORED NEXT TO WELLHEAD. REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f.



PHOTO 22: APPEARS TO BE A SEPARATOR INSIDE GARAGE STYLE BUILDING ON LOCATION. THERE IS ALSO A TRACTOR STORED INSIDE BUILDING. (TRACTOR IS OWNED BY MR. SANDIBAL THE LAST LAND OWNER)



Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



Colorado Oil & Gas Conservation Commission
37.1093, -104.33945, 1873.0m, 53°
2020/06/12 10:57:42

PHOTO 23: UNUSED EQUIPMENT STORED INSIDE GARAGE STYLE BUILDING. REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f.



Colorado Oil & Gas Conservation Commission
37.10909, -104.33968, 1869.0m, 228°
2020/06/12 10:59:03

PHOTO 24: UNUSED EQUIPMENT AND TRASH OF LOCATION NEAR CARPORT STYLE BUILDING. REMOVE UNUSED EQUIPMENT, TRASH AND DEBRIS, COMPLY WITH RULE 603.f.



Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 25: BATTERY OF 55 GAL. DRUMS ON EAST SIDE OF GARAGE STYLE BUILDING. REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f.



PHOTO 26: LABEL ON 55 GAL. DRUM IN EAST BATTERY.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899




PHOTO 27: LABEL ON 55 GAL. DRUM IN EAST BATTERY



PHOTO 28: LABEL ON 55 GAL. DRUM IN EAST BATTERY.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 29: APPEARS THAT 1 OR MORE OF THE 55 GAL. DRUMS IN EAST BATTER ARE LEAKING FLUID. CANNOT DETERMINE WHICH BARRELS OR BARRELS ARE LEAKING. (IT APPEARS THAT IT COULD BE USED OIL ON THE PALLETS AND GROUND NEAR BARRELS).



PHOTO 30: UNUSED RISER ON EAST SIDE OF GARAGE STYLE BUILDING. REMOVE UNUSED RISER COMPLY WITH NTO AND RULE 603.f.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 31: UNUSED EQUIPMENT ON SOUTH SIDE OF GARAGE STYLE BUILDING. REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f.



PHOTO 32: UNUSED MIS. PIPES STORED ON NORTH SIDE OF LOCATION (2 7/8" TBG AND APPEARS TO BE 6" CSG.). REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



PHOTO 33: CELLAR CONTAINING A VALVE THAT APPEARS TO BE CLOSED . (THIS IS THE VALVE THAT CONTROLS THE LEAKING POLLY PIPE THAT RUNNS FROM THIS CELLAR ACROSS LOCATION TO APP. 300' TO THE SOUTH OF LOCATION WHERE THERE IS A SLIGHT LEAK, THIS IS THE LINE THAT USED TO SUPPLY A HOUSE THAT IS A FEW HUNDRED YARDS TO THE SOUTH OF LOCATION). THE LINE HAS BEEN CUT AT THE PROPERTY LINE BY THE NEW LANDOWNER.



PHOTO 32: PHOTO 35: DISTANCE FROM LEAK TO NEAREST BUILDING (SOUTHERN MOST BUILDING ON LOCATION) APP. 222'. DISTANCE FROM NEXT CLOSEST BUILDING (RANCH OWNED BUILDING APPEARS TO BE TOOL SHED) APP. 339' AND DISTANCE FROM NEXT BUILDING (LARGE SHOP OWNED BY LANDOWNER) 324'.

Inspection Photos
Location Name: MARAH 1
API#: 05-071-09451
INSP. #: 695102899



**PHOTO 35: DISTANCE FROM LEAK TO NEAREST BUILDING
(SOUTHERN MOST BUILDING ON LOCATION) APP. 222'.
DISTANCE FROM NEXT CLOSEST BUILDING (RANCH OWNED
BUILDING APPEARS TO BE TOOL SHED) APP. 339' AND
DISTANCE FROM NEXT BUILDING (LARGE SHOP OWNED BY
LANDOWNER) 324'.**