



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	corrective date
Type: Progressive Cavity	# 1	Comment:	Corrective Action:	Date:
Type: Gas Meter Run	# 1	Comment: CAL. REPORT SHOWS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.	Corrective Action:	Date:
Type: Ancillary equipment	# 1	Comment: TELEMETRY EQUIPMENT	Corrective Action:	Date:
Type: Deadman # & Marked	# 3	Comment: ALL HAVE MARKERS	Corrective Action:	Date:
Type: Vertical Separator	# 1	Comment:	Corrective Action:	Date:
Type: Prime Mover	# 1	Comment:	Corrective Action:	Date:
Type: Bradenhead	# 1	Comment: IS PLUMBED TO SURFACE	Corrective Action:	Date:

**Venting:**

Yes/No	NO	Corrective Action:	Date:
Comment:			

**Flaring:**

Type	
------	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 261446 Type: WELL API Number: 071-07497 Status: PR Insp. Status: PR

**Producing Well**

Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695102912	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5184132">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5184132</a>