

Inspection Photos
Operator: BP America
API: 067-09400
Date: 6/24/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing within portions of the interim reclamation area with crested wheatgrass, intermediate wheatgrass, and western wheatgrass, but remains sparse in portions and needs to be monitored.



Photo 3. View of the reference area, comprised of irrigated grass field.