

Inspection Photos
Operator: BP America
API: 067-08954
Date: 6/24/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of kochia plants in the western project area; wilting, after what appears to be herbicide treatment.



Photo 3. View of wilting musk thistles within the southern project area.



Photo 4. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing here with grasses such as western wheatgrass and crested wheatgrass. Weeds need to continue to be managed.



Photo 5. View of the reference area, comprised of irrigated grass field.