

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2020

Submitted Date:

06/26/2020

Document Number:

700700976

FIELD INSPECTION FORM

 Loc ID 334716 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
, COGCC		michael.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259724	WELL	PR	09/28/2001	GW	045-07774	UNOCAL GM 240-1	PR
264291	WELL	PR	01/13/2003	GW	045-08204	WILLIAMS GM 41-1	PR
264292	WELL	PR	01/13/2003	GW	045-08205	WILLIAMS GM 341-1	PR
291035	WELL	PR	06/13/2007	GW	045-14262	WILLIAMS GM 344-36	PR
291036	WELL	PR	06/13/2007	GW	045-14261	WILLIAMS GM 441-1	PR

General Comment:

COGCC Inspection Report Summary

On Monday 6/22/20 at approximately 11:30 AM, I, Inspector Scott Ramsey, conducted an inspection on site in response of Complaints 18200448946, 18200448939, 18200448940 at TEP GM 240-1, at Location # 334716 in Garfield Colorado.

While there, I observed normal production operations. No evidence of odor. Winds are calm. Production tanks are open to atmosphere through pipe on top of tank, no anardo valve, thief hatch is closed.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:

Equipment:		corrective date
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 5	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	methanol tank at seperators	
Corrective Action:		Date:
Type: Plunger Lift	# 5	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 5	
Comment:	All meters calibrated on location within a year.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLS	STEEL AST		,
Comment:	shared containment with condensate tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:				
Yes/No	YES			
Comment:	Production tank is open to atmosphere through pipe on top of tank, no anardo valve, thief hatch is closed.			
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	259724	Type:	WELL	API Number:	045-07774	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing							Date:	
Corrective Action:								Date:	
Complaint									
Comment:	Complaints 18200448946, 18200448939, 18200448940							Date:	
Corrective Action:								Date:	
Facility ID:	264291	Type:	WELL	API Number:	045-08204	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing							Date:	
Corrective Action:								Date:	
Complaint									
Comment:	Complaints 18200448946, 18200448939, 18200448940							Date:	
Corrective Action:								Date:	
Facility ID:	264292	Type:	WELL	API Number:	045-08205	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing							Date:	
Corrective Action:								Date:	
Complaint									
Comment:	Complaints 18200448946, 18200448939, 18200448940							Date:	
Corrective Action:								Date:	
Facility ID:	291035	Type:	WELL	API Number:	045-14262	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing							Date:	
Corrective Action:								Date:	
Complaint									
Comment:	Complaints 18200448946, 18200448939, 18200448940							Date:	
Corrective Action:								Date:	
Facility ID:	291036	Type:	WELL	API Number:	045-14261	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing							Date:	
Corrective Action:								Date:	
Complaint									
Comment:	Complaints 18200448946, 18200448939, 18200448940							Date:	
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Culverts				
Gravel		Ditches				
		Rip Rap				
Berms		Berms				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700981	photos for GM 240-1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5185668