

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Ancillary equipment	# 1	Comment: TELEMETRY EQUIPMENT	Corrective Action:	Date:	
Type: Vertical Separator	# 1	Comment:	Corrective Action:	Date:	
Type: Gas Meter Run	# 1	Comment: CAL. REPORT SHOWS CALIBRATION WITHIN LAST YEAR,	Corrective Action:	Date:	
Type: Deadman # & Marked	# 4	Comment: ALL HAVE MARKERS	Corrective Action:	Date:	
Type: Progressive Cavity	# 1	Comment:	Corrective Action:	Date:	
Type: Prime Mover	# 1	Comment: ENGINE SKID	Corrective Action:	Date:	
Type: Bradenhead	# 1	Comment: IS PLUMBED TO SURFACE	Corrective Action:	Date:	

Venting:

Yes/No	NO	Corrective Action	Date

Flaring:

Type			

Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 217751 Type: WELL API Number: 071-06530 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695102922	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5185930